National Transportation Safety Board NTSB ID: IAD96LA066 Aircraft Registration Number: N776FE FACTUAL REPORT Occurrence Date: 04/23/1996 Most Critical Injury: None Occurrence Type: Accident Investigated By: NTSB ETYBO Location/Time Nearest City/Place State Zip Code Local Time Time Zone 2141 DC 20041 **EDT** WASHINGTON Distance From Landing Facility: Direction From Airport: Airport Proximity: On Airport Aircraft Information Summary Aircraft Manufacturer Model/Series Type of Aircraft Cessna 208 Airplane

Narrative

Sightseeing Flight: No

Brief narrative statement of facts, conditions and circumstances pertinent to the accident/incident:

On April 23, 1996, at about 2141 eastern daylight time, a Cessna 208, N776FE, operated by Mountain Air Cargo, Inc., in Denver, North Carolina, sustained substantial when it tipped onto its left side while taxiing in gusty wind conditions at the Washington Dulles International Airport, in Washington, DC. The pilot, the sole occupant of the airplane, was not injured. Visual Meteorological Conditions prevailed, and an instrument flight plan was filed. The accident occurred while the pilot was taxiing the airplane to runway 30 for departure, with an intended destination of Richmond, Virginia.

Air Medical Transport Flight: No

The pilot reported: "After being cleared by the tower to taxi into position and hold on runway 30, the aircraft began to skid on the threshold markings causing the airplane to lose traction and the wing to raise up on the right side." He stated the airplane tipped over, coming to rest on the left wing and propeller. He reported that the wind continued to blow the airplane after it tipped, and it skidded off the runway onto the overrun. The pilot stated that the winds were out of 300 degrees at 17 knots, with gusts to 30 knots.

The pilot indicated that he felt like he had taken every precaution and that the cause of the accident was the gear starting to slide on the painted surface which was slick in spots from an earlier rain storm.

National Transportation Safety Board
FACTUAL REPORT
AVIATION

NTSB ID: IAD96LA066

Occurrence Date: 04/23/1996

7 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2												
AVIATION Occurren			rrence Typ	ence Type: Accident								
Landing Facility/Approach Information												
Airport Name	Airport ID:	Airport Eleva	tion	Run	Runway Used Run			h	Runw	vay Width		
WASHINGTON DULLES INTL			IAD	288 Ft	. MSL	30		1		150		
Runway Surface Type: Concrete												
Runway Surface Condition: Wet												
Type Instrument Approach: NONE												
VFR Approach/Landing: None												
Aircraft Information												
Aircraft Manufacturer Cessna			Mode 208	el/Series						Number 30273		
Airworthiness Certificate(s): Normal												
Landing Gear Type: Tricycle												
Homebuilt Aircraft? No	omebuilt Aircraft? No Number of Seats: 2					Certified Max Gross Wt.					of Engines: 1	
= 11				Engine Manufacturer: Model/Series P&W PT6A-114								d Power:
- Aircraft Inspection Information												
Type of Last Inspection	Date of La	Date of Last Inspection Time Sir			ince Last Inspection			Airfram	ne Tot	tal Time		
AAIP 0-				04/01/1996				28 Ho	ours		2	869 Hours
- Emergency Locator Transmitter (E	ELT) Information											
ELT Installed? Yes		ELT Aided in Locating Accident Site? No										
Owner/Operator Information												
Registered Aircraft Owner			Street	Address 3101 TC	HULA	НОМА						
FEDERAL EXPRESS CORPORATION				City MEMPHIS							е	Zip Code 38118
	MEMPHIS TN 38118 Street Address											
Operator of Aircraft PO BOX 488												
MOUNTAIN AIR CARGO INC.				City DENVER							e	Zip Code 28037
Operator Does Business As:	•	Operator Designator Code: MTNA										
- Type of U.S. Certificate(s) Held:												
Air Carrier Operating Certificate(s):	Cargo; Suppleme	ental; C	On-deman	d Air Taxi								
Operating Certificate:				Operator (Certific	ate:						
Regulation Flight Conducted Under	: Part 135: Air Ta	xi & Co	ommuter									
Type of Flight Operation Conducted	: Unknown											
		FACTU	JAL REP	ORT - AVIAT	ION							Page 2

National Transportation Safety Board

FACTUAL REPORT

AVIATION

NTSB ID: IAD96LA066

Occurrence Date: 04/23/1996

AVIATI	cident											
First Pilot Information												
Name			City			Sta	ate	Date of Birth	Age			
On File			On File			On	File	On File	35			
Sex: M Seat Occupied	: Left	Prir	ncipal Profes	n Pilot	Certificate Number: On File							
Certificate(s): Airline Transport												
Airplane Rating(s): Multi-engine Land; Single-engine Land												
Rotorcraft/Glider/LTA: None												
Instrument Rating(s): Airplane												
Instructor Rating(s): None												
Type Rating/Endorsement for Accident/Incident Aircraft? No Current Biennial Flight Review?												
Medical Cert.: Class 2	Medica	al Cert. Status	s: Valid Me	dicalno wa	ivers/lim.		Date of	Last M	ledical E	Exam: 10/02/19	95	
- Flight Time Matrix	Flight Time Matrix All A/C This Make and Model Airplane Airplane Mult-Engine Mult-Engine						strument Simulated		Rotorcraft	Glider	Lighter Than Air	
Total Time	5241 2840 5162 79		1898	40	1	75						
Pilot In Command(PIC)			5	33)	65						
Instructor	1200	400	1200		270	4	_	\dashv				
Last 90 Days Last 30 Days	102 37	102 37	102 37		102 37	1	9 3					
Last 24 Hours 1 1 1							1	\dashv				
Last 24 Hours 1 1 1 1 1 1 1 1 1 1 Seatbelt Used? Yes Shoulder Harness Used? Yes Toxicology Performed? No Second Pilot? No)		
Choulder Harriess Oscar: 163												
Flight Plan/Itinerary												
Type of Flight Plan Filed: IF	R											
Departure Point	State	Aiı	Airport Identifier Departu			rture Time	Time Zone					
Same as Accident/Incide		IA	D		0000							
Destination	State	Aiı	Airport Identifier									
RICHMOND	VA	RI	RIC									
Type of Clearance: IFR												
Type of Airspace:												
Weather Information												
Source of Briefing: Flight Service Station												
Method of Briefing:												
FACTUAL REPORT - AVIATION Page 3												

National Transportation Safety Board FACTUAL REPORT AVIATION

NTSB ID: IAD96LA066

Occurrence Date: 04/23/1996

ETYBOR				Occurrence Type: Accident										
Weather	Information													
WOF ID	Observation Time	Time Zone	wo	F Elevati	on	WOF Distance From Accid			dent Site Direction From Accident			n Accident Sit	e	
				000 =					0 NM					
IAD	2150	EDT		288 Ft. MSL							0 Deg. Mag.			
Sky/Lowes	t Cloud Condition: Scat	tered					6000 Ft. AGL			Condition of Light: Night/Bright				
Lowest Ce	iling: Broken		8	8500 Ft. AGL			ility:	20	SM		meter:	29.00	"Hg	
Temperature: 15 °C Dew Point:				7 °C	Direction	300			De	nsity Altitude:		Ft.		
Wind Spee	ed: 20	Gusts: (30	Weather Condtions at Accident					ite: Visual C	Cond	itions			
Visibility (F	RVR): 0 Ft.	Visibility	(RVV)	0	SM	SM Intensity of Precipitation: Unknown								
Restriction	s to Visibility: None													
Type of Pro	ecipitation: None													
Accident Information														
Aircraft Damage:				Aircraft Fire:					Aircraft Explosion					
Classificati	on:													
- Injury Su	mmary Matrix	atrix Fatal Seri		rious Minor		None	TOTAL							
First Pi	lot					1		1						
Second	d Pilot													
Studen	t Pilot							\neg						
Flight I	nstructor													
Check	Pilot													
Flight E	ngineer													
Cabin A	Attendants				\neg			\neg						
Other C	Crew				\neg									
Passen	igers													
- TOTAL A	ABOARD -					1		1						
Other 0		0		0	0	<u> </u>		0						
- GRANE	TOTAL -	0		0	0	1		1						
								- 1						

National Transportation Safety Board

FACTUAL REPORT AVIATION

NTSB ID: IAD96LA066

Occurrence Date: 04/23/1996

Occurrence Type: Accident

Administrative	

Investigator-In-Charge (IIC)

BUTCH WILSON

Additional Persons Participating in This Accident/Incident Investigation:

SAM STREET DULLES INT'L AIRPORT, GT BLDG WASHINGTON, DC 20041